

## Assembly instructions 09/2022

### TOOLS:

Allen key (enclosed) / cordless screwdriver

3x/4x countersunk bolts (M10x20)



6x/8x countersunk bolts (M6x16)




3x/4x Spax screws (5x20)




amount of fasteners depends on the shape of the tabletop: round, triangular and freeform (3 legs), rectangular (4 legs)

Assemble the table on a **soft surface (e.g. blanket)** to avoid damage.




- 1 legs (3 or 4)
- 2 mounting plates (3 or 4)
- 3 tabletop


1. Screw the mounting plates (2) onto the legs (1) using countersunk bolts (M10).



2. Secure the mounting plates by screwing the Spax screw into the provided holes.



3. Place the legs in the milled pockets on the underside of the tabletop (3).



4. Fix the mounting plates with screws.

